

Date: Friday, 10/10/2008 10:51:05 AM
User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: CUSTOM
Job Number	: 42529		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D205523011
This Issue	: 10/10/2008 S.O. No. :	Drawing Number	: D205523011
Prsht Rev.	: NC	Project Number	:
First Issue	: / / Type : MACHINED PARTS	Drawing Revision	:
Previous Run	: 00015	Material	:
Written By	:	Due Date	: 10/10/2008 Qty: 1 Um: Each
Checked & Approved By	: <u>MF 0810-10</u>		
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

PULL FROM STOCK D205-523-011 QTY 1 B 9866

WHILE DOING THE TESTING, NEED TO SCRAP THE OLD BOLTS, WASHERS AND NUTS AND
REPLACE WITH NEW ONES

REPACKAGE AND RETURN TO STOCK WITH SAME BATCH NUMBER

JS 08/10/15 (x1)

2.0	AN513A	Bolt
-----	--------	------



*etait déjà dans le kit
MAIS de ne l'ai pas sortie*



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Bolt

M15928

54

3.0	AN960JD516	Washer
-----	------------	--------



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Washer

M109059

x8.

54

4.0	MS21042L5	Nut
-----	-----------	-----



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Nut

M108161

x4.

8/10/14

(x)

54

Date: Friday, 10/10/2008 10:51:05 AM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: CUSTOM

Job Number: 42529

Part Number: D205523011

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/10/15

08/10/14

6.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/10/16

08/10/15

Job Completion



5.1
RETURN TO
STOCK WITH
SAME BATCH #

MF 08-10-16